



ATTENTION JCK EXHIBITORS!

Electrical Labor Requirements

Sands Expo & Convention Center

When is labor needed??

Labor is required for:

- A. All under-carpet distribution of electrical wiring.
- B. All overhead distribution of electrical wiring, including coaxial cable, fiber optics, CAT5, etc., and the distribution of same from product to booth and from booth-to-booth.
- C. Installation of electrical lighting packages anywhere but the front of the booth. If lighting packages are setup at the front of the booth, labor is included. If lighting needs to go in the back or along the sides, additional labor must be ordered.
- D. If your showcase is not provided by Levin then you will need to order labor for the setup of your power.
- E. If your booth is hard-walled then you will need to order additional labor for all lighting packages.

Straight time rates apply to labor calls between the hours of 8:00 a.m. and 5:00 p.m. Monday through Friday. Overtime rates apply to labor calls before 8:00 a.m. and after 5:00 p.m. Monday through Friday, Saturdays, Sundays, and Holidays. A minimum charge of 1.5 hours is applicable to all labor requests.

Billing will be done on a time and material basis.

Please complete the SES Electrical Labor Order Form to place your order.

Every effort will be made to dispatch electricians as requested, but start/install times cannot be guaranteed.

***Fax all order forms to our
Order Processing Department at 702-733-5568***

For additional questions, please call Customer Service at 702-733-5070